

## Subdivisions of T. 28 S. R. 3 W.

CHAINS	
	<p>A cedar, 24 ins. diam., bears N.72*W., 51 lks. dist. marked T 28 S R 3 W S 23 B T.</p> <p>Land mountainous. Soil, rocky, 4th. rate. Timber, cedar, fir and hemlock. Underbrush, willows, rhododendrons and young firs. Land mountainous, covered with dense underbrush of heavily timbered and exceptionally difficult to survey. May 26, 1910.</p>
	<p>At cor. secs. 23, 24, 25 and 26, Thence I run East on random line bet. secs. 24 and 25.</p>
40.00	Set temp. 1/4 sec. cor.
79.72	Intersect N. and S. line, 10 lks. S. of cor. secs. 19, 24, 25 and 30, Thence I run South 89*56'W. on true line bet. secs. 24 and 25, through heavy timber and dense underbrush. Ascend East slope.
11.00	Top of ridge, bears N. and S., descend W. slope.
19.60	Creek, 4 lks. wide, flows NW., ascend E. slope.
21.70	Trail, bears NW. and SE.
39.86	Set stone, 8x12x16 ins., 11 ins. in the ground, for 1/4 sec. cor., marked 1/4 on N. face, from which: A fir, 40 ins. diam., bears N.40*W., 53 lks dist. marked 1/4 S 24 B T. A fir, 24 ins. diam., bears S54*W., 206 lks. dist. marked 1/4 S 25 B T. House, Scott Morrison, bears S.50*E., 2 chs. At this cor. set off 21*16'N. on decl. arc.
53.80	Top of ridge, bears N. and S., descend NW. slope.
72.95	Creek, 3 lks. wide, flows NW.