

Subdivisions of T.28 S.R. 3 W.

CHAINS	
	I destroy markings on bearing trees referring to secs., 23 and 24.
	Cor. secs. 23 and 24. Thence I run South 1'E. on true line bet. secs. 23 and 24, through dense underbrush and heavy timber. Descend SE. slope.
2.00	Creek, 2 lks. wide, flows NE., ascend N. slope.
21.80	Morrison & Tuttle trail, bears NE and SW.
35.31	Set stake, 3 ft. long, 4 ins. sq., 24 ins. in the ground for 1/4 sec. cor., marked 1/4 S 23 on W., and 24 on E. face, from which: A yew, 10 ins. diam., bears N.79'E., 45 lks. dist. marked 1/4 S 24 B T. A fir, 40 ins. diam., bears W., 20 lks. dist. marked 1/4 S 23 B T.
36.27	Creek, 4 lks. wide, flows E., ascend N. slope.
41.40	Creek, 2 lks. wide, flows E., ascend E. slope.
70.00	Ascend N. slope.
75.31	Cor. secs. 23, 24, 25 and 26. Land, mountainous. Soil, rocky, 4th. rate. Timber, fir, cedar, yew and hemlock. Underbrush, rhododendrons, vine maple and young firs. Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.
	May 28, 1910
	Cor. secs., 26, 27, 34 and 35. Thence I run South 2'E. on true line bet. secs. 34 and 35, through dense underbrush and heavy timber. Ascend NE Slope.
3.40	Top of ridge, bears E. and W., descend SE. slope.