

Subdivisions of T.28 S R 3 W.

CHAINS	
40.00	Set granite stone, 6x8x14 ins., 10 ins. in the ground for 1/4 sec. cor. marked 1/4 on W. face, from which: A cedar, 24 ins. diam., bears S.35*W., 11 lks dist. marked 1/4 S 34 B T. A cedar, 10 ins. diam., bears S.74*E., 42 lks dist. marked 1/4 S 35 B T.
47.00	Descend S. slope.
56.00	Descend SE. slope.
68.60	Ascend NE slope.
76.00	Top of ridge, bears SE. and NW., descend S. slope.
79.01	Intersect S. bdy., 370 lks. S.89*18'W. of N. 1/4 Cor. Sec. 2. Set fir stake, 3 ft. long, 4 ins. sq., 24 ins. in the ground for closing cor. secs. 34 and 35, marked C C T 28 S R 3 W on N., S 35 on E., and S 34 on W. face, with 2 grooves on E. and 4 grooves on W. face, from which: A fir, 6 ins. diam., bears N.52*E., 20 lks. dist. marked T 28 S R 3 W S 35 B T. A laurel, 6 ins. diam., bears N.48*W., 28 lks dist. marked T 28 S R 3 W S 34 B T. Land, mountainous. Soil, rocky; 4th rate. Timber, cedar, fir and matherone. Underbrush, young firs, and rhododendrons. Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.
<hr/>	
	From the cor. secs. 26, 27, 34 and 35. I run North 2' W. on true line bet. secs. 26 and 27, through dense underbrush and heavy timber, descend NE. slope.
0.50	Creek, 2 lks. wide, flows E., ascend SE. slope.
20.35	Trail, bears E. and W.