

## Subdivisions of T 28 S R 3 W.

CHAINS	
24.00	Ascend S. slope.
40.00	Set granite stone, 6x8x15 ins., 10 ins. in the ground for 1/4 sec. cor., marked 1/4 on W. face, from which: A cedar, 14 ins. diam., bears N.62*W., 7 lks. dist. marked 1/4 S 27 B T. A fir, 6 ins. diam., bears N. 54*E., 35 lks. dist. marked 1/4 S 26 B. T.
80.00	Set stone, 6x10x15 ins., 10 ins. in the ground for cor. secs. 22,23,26 and 27, marked with 2 notches on S. and E. edges, and raise mound of stone, 2 ft. base, 1-1/2 ft. high, W. of cor., from which: A fir, 8 ins. diam., bears S.47*E., 14 lks. dist. marked T 28 S R 3 W S 26 B T. A fir, 8 ins. diam., bears S.56*W., 47 lks. dist. marked T 28 S R 3 W S 27 B T. A fir, 10 ins. diam., bears N.55*W., 10 lks dist. marked T 28 S R 3 W S 22 B. T. no other tree fit to mark.
	Land, mountainous. Soil, rocky; 4th rate. Timber, cedar, fir, hemlock and matherone. Underbrush, young firs, rhododendrons and willows. Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey. <p style="text-align: right;">May 29, 1910.</p>
	Cor.Secs., 22, 23, 26 and 27. Thence I run East on random line bet. secs. 23 and 26. 40.00 Set temp. 1/4 sec. cor. 80.02 Intersect N. and S. line, 16 lks. N of cor. secs. 23, 24, 25 and 26. Thence I run North 89*53'W. on true line bet. secs. 23 and 26. through