

Subdivisions of T. 28 S R 3 W.

CHAINS	
	<p>A laurel, 6 ins. diam., bears N.43*W., 27 lks. dist. marked 1/4 S 27 B T.</p>
70.62	Creek, 6 lks. wide, flows SW., ascend SE. slope.
75.40	Trail and top of ridge, bears S.W. and NE., descend W. slope.
80.00	<p>Set granite stone, 7 x 10 x 15 ins., 10 ins, in the ground for cor. secs. 27, 28, 33 and 34, marked with 3 notches on E. and 1 notch on S. edge; from which</p> <p>A fir, 42 ins. diam., bears N.10*E., 12 lks dist. marked T 28 S R 3 W S 27 B T.</p> <p>A cedar, 30 ins. diam., bears S.80*E., 50 lks dist. marked T 28 S R 3 W S 34 B T.</p> <p>A cedar, 30 ins. diam., bears S.61*W., 61 lks dist. marked T 28 S R 3 W S 33 B. T.</p> <p>A fir, 30 ins. diam., bears N.47*W., 58 lks. dist. marked T 28 S R 3 W S 28 B T.</p> <p>Land, mountainous. Soil, rocky: 4th rate. Timber, fir, cedar, laurel and hemlock. Underbrush, rhododendrons, young firs, vine maple. Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.</p>
	<p>Thence I run</p> <p>South 2'E. on true line bet. secs. 33 and 34, through dense underbrush and heavy timber; ascend N.slope.</p>
13.80	Top of ridge, bears NW. and SE., descend SW. slope.
27.10	Creek, 2 lks. wide, flows NW., ascend N. slope.
40.00	<p>Set granite stone, 6 x 8 x 15 ins., 10 ins. in the ground for 1/4 sec. cor., marked 1/4 on W. face; from which</p> <p>A laurel, 10 ins. diam., bears N.52*E., 10 lks dist. marked 1/4 S 34 B T.</p> <p>A fir, 24 ins. diam., bears N.44*W., 22 lks dist. marked 1/4 S 33 B T.</p>