

## Subdivisions of T 28 S R 3 W.

CHAINS	
	<p style="text-align: center;">S marked T 28 S R 3 W<sub>A</sub> 20 B T.</p> <p>Thence I run.</p> <p>South 3'E. on true line bet. secs. 20 and 21.</p> <p>Through dense underbrush and heavy timber, ascend N. slope.</p>
15.88	Top of ridge, bears E. and W.
25.48	Creek, 4 lks. wide, flows W., ascend N. slope.
35.68	<p>Set fir stake, 3 ft. long, 4 ins. sq., 24 ins. in the ground for 1/4 sec. cor., marked 1/4 S 20 on W. and 21 on E. face, from which:</p> <p style="padding-left: 40px;">A fir, 8 ins. diam., bears S.17'E., 23 lks dist. marked 1/4 S 21 B. T.</p> <p style="padding-left: 40px;">A fir, 7 ins. diam., bears S.15'W., 25 lks. dist. marked 1/4 S 20 B T.</p>
49.68	Top of ridge, bears E. and W., descend S. slope.
62.18	Creek, 2 lks. wide, flows W.
65.48	Top of ridge, bears E. and W., descend S. slope.
69.18	Creek, 2 lks. wide, flows W., ascend N. slope.
72.88	Top of ridge, bears E. and W., descend S. slope.
75.68	<p>Cor. secs. 20,21,28 and 29.</p> <p>Land, mountainous.</p> <p>Soil, rocky- 4th rate.</p> <p>Timber, cedar, fir, matherone and hemlock.</p> <p>Underbrush, rhododendrons, vine maple and young firs.</p> <p>Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.</p>
	<p>From the cor. secs. 29, 30, 31 and 32,</p> <p>I run</p> <p>North 4'W. on true line bet. secs. 29 and 30.</p> <p>Descend N. slope.</p>
3.10	Creek, 3 lks. wide, flows NW., ascend S. slope.
9.10	Top of ridge, bears E. and W., descend S. slope.