

Subdivisions of T. 28 S R 3 W.

CHAINS	
40.00	<p>Set fir stake, 3 ft. long, 4 ins. sq., 24 ins. in the ground for 1/4 sec. cor., marked 1/4 S 17 on W. and 16 on E. face, from which:</p> <p>A hemlock, 8 ins. diam., bears W., 37 lks. dist. marked 1/4 S 17 B T.</p> <p>A maple, 6 ins. diam., bears N.88°E., 12 lks dist. marked 1/4 S 16 B. T.</p>
44.90	Creek, 2 lks. wide, flows NW., ascend SW. slope.
64.50	Top of ridge and trail, bears NW. and SE., descend N. slope.
80.00	<p>Set fir stake, 3 ft. long, 4 ins. sq., 24 ins. in the ground for cor. secs. 8,9,16 and 17, marked T 28 S S 9 on NE., R 3 W S 16 on SE., S 17 on SW. and S 8 on NW. face, with 4 notches on S. and E. edges, from which:</p> <p>A hemlock, 5 ins. diam., bears N.63°E., 45 lks. dist. marked T 28 S R 3 W S 9 B T.</p> <p>A cedar, 24 ins. diam., bears S.67°E., 51 lks. dist. marked T 28 S R 3 W S 16 B T.</p> <p>A hemlock, 4 ins. diam., bears S.34°W., 35 lks. dist. marked T 28 S R 3 W S 17 B T.</p> <p>A cedar, 30 ins. diam., bears N.37°W., 65 lks. dist. marked T 28 S R 3 W S 8 B T.</p>
	Land, mountainous.
	Soil, rocky- 4th rate.
	Timber, cedar, fir, hemlock and matherone.
	Underbrush, rhododendrons, vine maple and young firs.
	Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.

June 13, 1910.