

## Subdivisions of T. 28 S. R. 3 W.

CHAINS	
	At cor. secs. 8,9,16 and 17,
	Thence I run
	North 89°41'E. on random line bet. secs. 9 and 16.
40.00	Set temp. 1/4 sec. cor.
80.50	Intersect N. and S. line, 50 lks. N. of cor. secs. 9, 10,15 and 16, which is a stake marked and witnessed, as described by the Surveyor General.
	Thence I run
	North 89°58'W. on true line bet. secs. 9 and 16.
	Through dense underbrush and heavy timber.
	Descend W. slope.
19.00	Cabin, bears S., 30 lks. dist.
29.00	Cabin, Joe Donnell, bears S., 30 lks. dist.
40.10	Cabin, W. Morris, bears S., 110 lks. dist.
40.25	Set stone, 6 x 8 x 14 ins., 10 ins. in the ground for 1/4 sec. cor., marked 1/4 on N. face, from which: A fir, 48 ins. diam., bears S.14°E., 38 lks. dist. marked 1/4 S 16 B T. A hemlock, 24 ins. diam., bears N.17°E., 58 lks dist. marked 1/4 S 9 B.T.
45.50	Creek, 6 lks. wide, flows N., ascend E. slope.
67.00	Top of ridge, bears N. and S., descend W. slope.
75.00	House, D. S. Morrison, bears S., 15 lks. dist.
77.50	Creek, 8 lks. wide, flows NW., ascend NE. slope.
80.50	Cor. secs. 8,9,16 and 17. Land, mountainous. Soil, rocky- 4th. rate. Timber, cedar, fir, hemlock and matherone. Underbrush, rhododendrons, young firs, vine maple and greasewood. Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.