

Subdivisions of T. 28 S., R. 3 W.

CHAINS	<p>Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.</p> <p style="text-align: right;">June 15, 1910.</p>
	<p>At cor. secs. 3,4,9 and 10.</p>
	<p>Thence I retrace</p>
	<p>North bet. secs. 3 and 4.</p>
39.94	<p>1/4 sec. cor., which is a stake marked and witnessed as described by the Surveyor General.</p>
78.24	<p>Closing cor. secs. 3 and 4, which is a stake marked and witnessed as described by the Surveyor General.</p>
	<p>Thence from the cor. secs. 4,5,8 and 9,</p>
	<p>I run</p>
	<p>North 1'W. on true line bet. secs. 4 and 5, through dense underbrush and heavy timber.</p>
	<p>Ascend S. slope.</p>
3.00	<p>Top of ridge, bears E. and W., descend N. slope.</p>
26.20	<p>Ravine, bears E., ascend S. slope.</p>
28.50	<p>Top of ridge, bears E. and W., descend N. slope.</p>
	<p>House, A Belchoir, bears E., 12 chs.</p>
36.00	<p>Trail, bears SE. and NW.</p>
40.00	<p>Set granite stone, 6 x 10 x 14 ins., 10 ins. in the ground for 1/4 sec. cor., marked 1/4 on W. face, from which:</p>
	<p style="padding-left: 40px;">A hemlock, 18 ins. diam., bears N.66*E., 27 lks.dist. marked 1/4 S 4 B T.</p>
	<p style="padding-left: 40px;">A fir, 30 ins. diam., bears N. 45*W., 27 lks.dist. marked 1/4 S 5 B T.</p>
	<p>Ascend South slope.</p>
52.50	<p>Top of ridge, bears NE. and SW., descend NE slope.</p>
67.00	<p>Creek, 8 lks, wide, flows SE., ascend S. slope.</p>
78.24	<p>Intersect Sixth Standard Parallel, 65 lks. E. of cor. secs. 32 and 33, which is a stake marked and witnessed as described by the Surveyor General.</p>
	<p>Set fir stake, 3 ft. long, 4 ins. sq., 24 ins. in the</p>