

Subdivisions of T. 28 S. R. 3 W.

CHAINS	
	<p>A cedar, 7 ins. diam., bears N.20*W., 39 lks dist. marked 1/4 S 7 B T.</p> <p>A cedar, 12 ins. diam., bears S.61*E., 42 lks. dist. marked 1/4 S 18 B T.</p>
53.00	Creek, 5 lks. wide, flows S., ascend W. slope.
54.00	House, Mary Hagan, bears S. 14 chs.
57.25	Top of ridge and trail, bears N. and S., descend SE. slope.
78.50	<p>Cor. secs. 7,8,17 and 18.</p> <p>Land, mountainous.</p> <p>Soil, rocky- 4th rate.</p> <p>Timber, fir, cedar and matherone.</p> <p>Underbrush, rhododendrons and young firs.</p> <p>Land mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey.</p>
	<p>Thence I run</p> <p>North 2*W. on true line bet. secs. 7 and 8.</p> <p>Through dense underbrush and heavy timber, ascend E. slope.</p>
5.00	House, U.Collins, bears E., 4 chs. dist.
25.25	Creek, 2-lks. wide, flows E., ascend SE. slope.
40.00	<p>Set cedar stake, 3 ft. long, 4 ins. sq., 24 ins. in the ground for 1/4 sec. cor., marked 1/4 S 7 on W. and 8 on E. face, from which:</p> <p>A cedar, 10 ins. diam., bears S.82*W., 12 lks dist. marked 1/4 S 7 B T.</p> <p>A hemlock, 12 ins. diam., bears S.21*E., 19 lks dist. marked 1/4 S 8 B T.</p>
63.60	Trail, bears NE. and SW.
65.70	Top of ridge bears E. and W., descend N. slope.
76.00	Creek, 2 lks. wide, flows NW., descend NW. slope.
80.00	Set cedar stake, 3 ft. long, 4 ins. sq., 24 ins. in the ground for cor. secs. 5,6,7 and 8, marked T 28 S S 5