

Subdivisions of T 28 S R 3 W.

CHAINS

on NE., R 3 W S 8 on SE., S 7 on SW., and S 6 on NW. face,
with 5 notches on E. and S. faces, from which:

A hemlock, 18 ins. diam., bears N.63*E., 13 lks. dist.
marked T 28 S R 3 W S 5 B T.

A hemlock, 20 ins. diam., bears S.3*E., 40 lks. dist.
marked T 28 S R 3 W S 8 B T.

A fir, 6 ins. diam., bears S.68*W., 20 lks dist.
marked T 28 S R 3 W S 7 B T.

A fir, 6 ins. diam., bears N.42*W., 16 lks dist.
marked T 28 S R 3 W S 6 B T.

Land, mountainous.

Soil, rocky- 4th. rate.

Timber, cedar, fir and matherone.

Underbrush, rhododendrons, young firs, greasewood and
willows.

Lead mountainous, covered with dense underbrush and
heavily timbered and exceptionally difficult to
survey.

Thence I run

South 89*58'E. on random line bet. secs, 5 and 8.

40.00 Set temp. 1/4 sec. cor.

79.98 Intersect, 50 lks. N. of cor. secs. 4,5,8 and 9.

Thence I run

North 89*37'W. on true line bet. secs. 5 and 8.

Through dense underbrush and heavy timber, ascend E. slope.

9.80 Top of ridge, bears E. and W., descend W. slope.

29.90 Creek, 2 lks. wide, flows SW., descend SW. slope.

39.99 Set cedar stake, 3 ft. long, 4 ins. sq., 24 ins. in the
ground for 1/4 sec. cor., marked 1/4 S 5 on N. and
8 on S. face, from which:

A maple, 10 ins. diam., bears N.10*W., 3 lks. dist.
marked 1/4 S 5 B. T.

A cedar, 5 ins. diam., bears S.12*W., 40 lks. dist.
marked 1/4 S 8 B. T.