

West Boundary of T: 28 S., R. 4 W.

<p>CHAINS</p> <p>80.80</p>	<p>White Oak, 8 ins. diam., bears S.1*E., 5.20 chs.</p> <p>Sec. corner to sec. 19, 30, 24 & 25</p> <p>Set new post as per instructions, bearing trees all standing viz.:</p> <p>Pine Tree, 18 ins. diam., bears N.80*E., 60 lks.</p> <p>Cedar Tree, 24 ins. diam., bears S.58*E., 52 lks.</p> <p>Pine Tree, 30 ins. diam., bears S.62½*W., 81 lks.</p> <p>Pine Tree, 12 ins. diam., bears N.16*W., 250 lks.</p> <p>Land chiefly mountainous, 3rd. rate</p> <p>Heavily Timbered, principally Fir, Cedar & Hemlock</p>
<p>35.00</p> <p>40.75</p>	<p>South on West Boundary of sec. 30</p> <p style="text-align: right;">Va. 14*50'E.</p> <p>Stream, 10 links wide, course E.</p> <p>¼ sec. cor., post set as per instructions, bearing trees all standing viz.: <u>SEE INSERT</u></p> <p>Fir Tree, 5 ins. diam., bears N.20*E., 2 lks.</p> <p>Fir Tree, 9 ins. diam., bears S.60*E., 16 lks.</p> <p>Fir Tree, 9 ins. diam., bears S.70*W., 20 lks.</p> <p>Laurel, 8 ins. diam., bears N.20*W., 14 lks.</p> <p>Land chiefly mountainous, 3rd. rate</p> <p>Heavily timbered, principally Fir, Cedar & Hemlock</p>
<p>10.00</p> <p>35.00</p> <p>41.10</p> <p>60.00</p> <p>75.00</p> <p>81.10</p> <p>81.15</p>	<p>South on West Boundary of sec. 31</p> <p style="text-align: right;">Va. 18* E.</p> <p>Top of Hill</p> <p>Foot of Hill</p> <p>¼ sec. corner, set new post as per instructions, bearing trees all standing viz.:</p> <p>Black Oak, 12 ins. diam., bears N.14½*W., 1.10 chs.</p> <p>Black Oak, 10 ins. diam., bears N.40*E., 45 lks.</p> <p>Top of Spur, descend W</p> <p>To base & begin to ascend</p> <p>Sec. corner to sec. 31, 36, 1 & 6, ^{and} corner to town 28</p> <p>& 29 S, R 4 & 5 W</p>

Trees for sec cor

Note Error in Bearing Trees No trees for 4 cor

PER Microfilm 2/17/1983