

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 28 S., R. 5 W.

CHAINS	
59.00	Bailey's fence, E. and W.
67.00	Bailey's fence, NW. and SE.
77.00	Bailey's house, 3.00 chs. East.
78.80	Bailey's fence, E. and W.
80.00	Set post with pile of stones around post. No trees in reasonable distance. A boulder, 3 feet diam., bears N.86*E., 448 lks. dist. A boulder 24 ins. diam., bears N.25*W., 300 lks. dist. This mile is open Oak ridges, mostly good grazing. North 20.00 chs. good tillage land, improved by J. Bailey. Timber, Oak, Pine, Fir and Laurel.
	East on Random between secs. 26 and 35. Va. 19*E.
40.00	Set temporary $\frac{1}{2}$ sec. corner and at
80.10	Intersect line at post. Ran West on true line.
8.00	Cleft of rocks 50 lks. left of line.
12.10	Summit of ridge. House and claim of B. Ways (house 1 ch. left of line).
40.05	Set post to $\frac{1}{2}$ sec. corner, from which A Laurel, 4 ins. diam., bears N.85*E., 6 lks. dist. A Fir, 4 ins. diam., bears S.37*W., 5 lks. dist.
80.10	Corner to secs. 26, 27, 34 and 35. This mile is heavily timbered and mountainous excepting about 13 chs. on the West end, which is open timber, Fir, Cedar, Pine, Laurel and Ash. Underbrush abundant. July 22, 1871.
	West on Random between secs. 27 and 34. Va. 19*E.
40.00	Set temporary $\frac{1}{2}$ sec. corner and at
80.00	Intersect line 75 lks. North of corner. Ran N.89*35'E. on true line.