

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 28 S., R. 5 W.

CHAINS	
	<p>A Laurel, 4 ins. diam., bears N.18*W., 37 lks. dist.</p> <p>A Laurel, 4 ins. diam., bears N.80*E., 30 lks. dist.</p> <p>A Laurel, 4 ins. diam., bears S.35*E., 49 lks. dist.</p> <p>A Laurel, 4 ins. diam., bears S.18*W., 40 lks. dist.</p> <p>This mile is on the West slope of Dodson mountain, principally covered with heavy timber, Fir, Cedar, Oak, Laurel, and Pine.</p> <p style="text-align: right;">July 24, 1871.</p>
	<p>East on Random between secs. 23 and 26.</p> <p style="text-align: right;">Va. 19*E.</p>
40.00	Set temporary $\frac{1}{4}$ sec. post and at
80.16	Intersected line 10 lks. North of corner.
	Ran N.89*54*W. on true line.
	Va. 19*E.
3.00	Fence, N. and S.
17.50	A creek, 2 lks. wide, Course SW.
33.00	A spring, 25 lks. right, Course S.
40.08	Set post to $\frac{1}{4}$ sec. corner, from which
	A W. Oak, 4 ins. diam., bears N.85*W., 35 lks. dist.
	A W. Oak, 3 ins. diam., bears S.35*E., 30 lks. dist.
62.20	A creek, 4 lks., Course NW.
80.16	Corner of secs. 22, 23, 26 and 27.
	<p>East half of this mile is good grazing for stock, open hills and scattering Oak and Pine trees. The West half is heavily timbered, principally Fir, Cedar, Laurel, Oak.</p>
	<p>West on Random between secs. 22 and 27.</p>
40.20	Intersect $\frac{1}{4}$ sec. post 20 lks. South of post.
	Run S.89*43'E. on true line from $\frac{1}{4}$ sec. post between secs. 22 and 27.
40.20	Corner to secs. 22, 23, 26 and 27.