

Subdivisions of T. 28 S., R. 5 W.

CHAINS

This $\frac{1}{2}$ mile is rough, principally timber and underbrush,
Fir, Cedar, Laurel and Oak.

North on Random between secs. 22 and 23.

Va. 19°E.

40.00 Set temporary $\frac{1}{4}$ sec. post and at

83.00 Intersect line 2.60 chs. East of corner.

Ran S.1°52'E. on true line.

Va. 19°E.

41.50 Set post to $\frac{1}{4}$ sec. corner, from which

A Laurel, 10 ins. diam., bears N.50°E., 23 lks. dist.

A Fir, 24 ins. diam., bears S.60°W., 35 lks. dist.

42.00 Dry gulch, West, leave Oak ridges and enter heavy timber.

56.00 Trail, NW. and SE.

60.00 A stream, 2 lks. wide, Course West.

69.00 A stream, 4 lks. wide, Course West.

83.00 Corner to secs. 22, 23, 26 and 27.

This mile heavily timbered on the North slope of Dodson
mountain. Valuable only for timber, which is Fir,
Laurel, Cedar, Spruce, Oak and Maple.

July 25, 1871.

General Description

Principally high and abrupt mountains separated by deep
canyons with a dense growth of heavy Fir, Pine and
Cedar timber, alternating on the South slopes. Canyons
are deep and brushy. Rocks principally granite, lava
and basalt with fragments of broken quartz. Some of
the ridges of open land are settled and good farms open-
ed. The open land is valuable for its grazing and the
remainder valuable for its first quality of timber.
Soil, generally rocky and mountain sides covered with
loosebroken shell rocks.