

County Surveyor's Record, Douglas County, Oregon

North Boundary of T. 28 S., R. 8 W.
 as surveyed by Dennis Hathorn, Deputy Surveyor,
 under Contract No. 57, dated April 12, 1855.

CHAINS	Beginning at the cor. of T. 28 S., Rs. 7 and 8 W. which is on the 6th Standard Parallel South. Thence, West, on North boundary of Sec. 1. <div style="text-align: right;">Va. 19* 35' E.</div>	
8.99	Cor. of T. 27 S., Rs. 7 and 8 W.	+50
37.00	Enter prairie, C. N. and S.	+50
40.00	Set $\frac{1}{4}$ sec. post, from which	+6
	A. B. Oak, 36 in. dia., bears S. 26* E., 339 lks.	
	A. W. Oak. 24 in. dia., bears N. 87* E., 331 lks.	
60.00	Enter Oak openings, C. N. and S.	+20
80.00	Set post, cor. of secs. 1 and 2, from which	+100
	A maple, 12 in. dia., bears S. 75* W., 65 lks.	
	A. B. Oak, 18 in. dia., bears S. 28* E., 42 lks.	
	Land, mostly hilly, oak openings.	
	Soil, second rate.	
	West, on North boundary of Sec. 2.	
	Va. 19 $\frac{1}{2}$ * E.	
50.00	Enter Fir timber and commence ascending S. slope of mountain.	-5
40.00	Set $\frac{1}{4}$ Sec. post, from which	+300
	A Fir, 15 in. dia., bears N. 8* E., 12 lks.	
	A Fir, 12 in. dia., bears S. 14* W., 13 lks.	
76.32	Spring branch, 5 lks. wide, C. NE..	-300
80.00	Set post, cor. Secs. 2 and 3, from which	+50
	A Hemlock, 12 in. dia., bears S. 80* E., 20 lks.	
	A Hemlock, 8 in. dia., bears S. 45* W., 23 lks.	
	Land, mountainous and in many places very steep and rocky. Well timbered with fir, and some hemlock and cedar.	
	Soil, third rate.	