

## East Boundary of T. 28 S., R. 8 W.

CHAINS		
	Land, about the same as last mile, with the exception of being more hilly.	
	South, between Secs. 18 and 13.	
		Va. 19 $\frac{1}{8}$ *E.
28.50	Summit of ridge, course East and West	+300
40.00	Set $\frac{1}{4}$ Sec. post, from which	
	A Fir, 12 in. diam., bears N.63*E., 9 lks. dist.	
	A Fir, 6 in. diam., bears N.34*W., 40 lks. dist.	
40.00	Old $\frac{1}{4}$ post bears N. 16.60 chs. and E. 3.37 chs.	
41.30	Branch, 5 lks. wide, course East.	-40
65.25	Summit of ridge, course East and West.	+250
80.00	Set post, cor. Secs. 18, 19, 13 and 24, from which	
	A Laurel, 18 in. diam., bears S.89 $\frac{3}{4}$ *W., 35 lks. dist.	
	A Laurel, 10 in. diam., bears N.45*W., 65 lks. dist.	
	A. B. Oak, 12 in. diam., bears S.35*E., 33 lks. dist.	
	A. B. Oak, 6 in. diam., bears N.32*E., 45 lks. dist.	
80.00	Old cor. bears N. 18.76 chs. and E. 2.05 chs.	
	Land, very hilly. Timber, Fir, Oak and Laurel.	
	Soil, third rate.	
		July 11, 1855.
	South, between Secs. 19 and 24.	
12.00	Commence descending rocky hill	+50
40.00	$\frac{1}{4}$ Sec. cor. Ground, so rocky that a post could not be driven.	-400
40.43	Marked a W. Oak, 3 in. diam., for witness to true cor.,	-2
	from which	
	A W. Oak, 6 in. diam., bears N.48*E., 37 lks. dist.	
	A W. Oak, 10 in. diam., bears S.75*W., 73 lks. dist.	
62.60	Old cor., Secs. 19, 30, 13 and 24 bears E. 158 lks.	+50
72.50	Cross dividing ridge, course NE. and SW.	+100
80.00	Set post, cor. of Secs. 19, 30, 24 and 25, from which	-60