

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 28 S., R. 8 W.

CHAINS 40.00	Set $\frac{1}{4}$ Sec. post, from which A Laurel, 15 ins. diam., bears N.35*E., 14 lks. dist. A Laurel, 12 ins. diam., bears S.60*W., 22 lks. dist.	-100
48.70	Branch, 20 lks. wide, course East	-150
65.00	Commence descending	+250
80.00	Set post, cor. Secs. 9, 10, 15 and 16, from which An Ash, 8 ins. diam., bears N.16*E., 33 lks. dist. A Fir, 36 ins. diam., bears N.69*W., 17 lks. dist. A Cedar, 15 ins. diam., bears S.31*W., 16 lks. dist. A Laurel, 8 ins. diam., bears S.13*E., 52 lks. dist. Land, uneven. Timber, principally, Fir. Soil, third rate.	-50
East, on random, between Secs. 10 and 15.		
40.00	Set temporary $\frac{1}{4}$ Sec. post.	
80.00	Intersect North and South line, 93 lks. South of cor.	
S.89*20'W. On true line, between Secs. 10 and 15.		
6.00	Leave Oak and enter Fir timber, course North and South	+20
10.25	Branch, 5 lks. wide, course South	-80
22.50	Summit of ridge, course North and South	+200
40.00	Set $\frac{1}{4}$ Sec. post, from which A Laurel, 12 ins. diam., bears S.71*E., 19 lks. dist. A Fir, 7 ins. diam., bears N.79*E., 28 lks. dist.	-50
49.00	Dry gulch, course SE.	-70
80.00	To cor. Land, uneven and for the most part covered with brush, consisting principally of Fir, and Laurel. Timber, Fir, Cedar and Laurel. Soil, second rate.	+80