

Subdivisions of T. 28 S., R. 8 W.

CHAINS	N.89*28'E. on true line, between Secs. 30 and 31.	
41.15	Set $\frac{1}{4}$ Sec. post, from which A Fir, 12 ins. diam., bears N.4*E., 82 lks. dist. A Fir, 10 ins. diam., bears S.36*W., 13 lks. dist.	-50
46.35	Branch, 6 lks. wide, course South.	-40
51.80	Branch, 5 lks. wide, course South.	-20
74.00	Branch, 5 lks. wide, course South.	+20
80.92	A Fir, 50 ins. diam.	-10
81.15	To cor.  Land, rolling; timber, Fir, Cedar and Laurel.  Soil, second rate.	

General Description.

The surface of this Tp. is very broken and the NW. portion, mountainous. A few little valleys are susceptible of cultivation. There are six claims taken in the Tp. and one sawmill in operation. The NW. portion of the Tp. is unfit for settlement or cultivation, and therefore not surveyed.

Sept. 18, 1855.

Subdivision of T. 28 S., R. 8 W.  
as surveyed by W.S. Chapman, Deputy Surveyor,  
under Contract No. 234, dated June 24, 1875.

Having adjusted my chain by the U.S. Standard at Portland, and having an accurate and well adjusted Solar Compass, I did not think it necessary to retrace any lines for testing my instruments.

Began at corner to Sections 2, 3, 10 and 11, established by previous survey, found post with witness trees, as follows, which agree with the notes furnished by the Surveyor General's office, to wit:

A Laurel, 5 ins. diam., bears N.89\*W., 29 lks. dist.