

## Subdivision of T. 28 S., R. 8 W.

CHAINS

A Laurel, 6 ins. diam., bears S.30°E., 3 lks. dist.

A Laurel, 7 ins. diam., bears S.36°W., 30 lks. dist.

A Fir, 20 ins. diam., bears N.81°E., 39 lks. dist.

North, on random line, between Secs. 2 and 3,

Va. 20°30'E.

40.00 Set temporary  $\frac{1}{4}$  Sec. post.80.12 Intersect T. line, 20 lks. West of post to cor. of 2 and 3.  
S.0°9'W. on true line.

0.52 Brook, 5 lks. wide, running East.

15.62 Faint trail on summit of ridge, NE. and SW.

18.00 Rock bluff, 70 ft. high, facing South.

23.00 Rock bluff, 200 ft. high, facing South.

32.12 Brook, 4 lks. wide in deep canyon, running East.

40.12 Set post 4 ft. long, 4 ins. diam. and one ft. in ground  
for  $\frac{1}{4}$  Sec. cor., from whichFir, 36 ins. diam., bears N.39 $\frac{1}{2}$ °E., 18 lks. dist.

Fir, 30 ins. diam., bears S.37°W, 21 lks. dist.

55.00 Cross ridge, running East.

69.00 Cross ridge, running East.

80.12 To cor. to Secs. 2, 3, 10 and 11.

Land, mountainous.

Soil, third rate, rocky.

Timber, Fir, Cedar, Laurel and Hemlock. Very poor quality.

July 24, 1875.

North, between Sec. 9 and 10,

Va. 20°30'E.

9.90 Trail, SW. and NE.

18.50 Trail NW. and SE.

25.00 Summit of hill.

30.00 Down hillside, facing NE.

36.40 Brook, 4 lks. wide, running SE.

40.00 Set post 4 ft. long, 4 ins. diam. and 1 ft. in ground,  
for  $\frac{1}{4}$  Sec. cor., from which