

Subdivisions of T. 28 S. R. 8 W.

CHAINS		Brook, almost dry in ravine, running NE.
51.00		
56.50		Brook, 2 lks wide, running East and NE.
79.80		Intersect post to corner of Secs. 16, 17, 20 and 21. Land, rolling and second rate. Timber, Fir, Cedar and Hemlock.
		July 29, 1875.
North, between Secs. 16 and 17.		
		Va. 20*15' E.
10.00		About 5 chs. West to Coos Bay Road.
36.60		Cross Coos Bay Road, extending N.30*W. and S.30*E.
40.00		Set post 4 ft. long, 4 ins. diam., 1 ft. in ground, for $\frac{1}{4}$ Sec. cor., from which A Fir, 4 ins. diam., bears S.61 $\frac{1}{2}$ *W., 72 lks. dist. A Fir, 12 ins. diam., bears N.71 $\frac{1}{2}$ *E., 40 lks. dist.
42.80		Cross brook, 2 lks. wide, running East by South, and begin ascent of steep hill.
55.00		Summit of high hill.
73.20		Brook, 3 lks. wide, running N. and NE.
78.10		Brook, 6 lks. wide, running Easterly.
80.00		Set post, four ft. long, 5 ins. diam. and 1 ft. in ground, on steep side of hill, facing South, for cor. of Secs. 8, 9, 16 and 17, from which A Fir, 50 ins. diam., bears S.62*E., 16 lks. dist. A W. Fir, 6 ins. diam., bears N.16 $\frac{1}{2}$ *E., 10 lks. dist. A W. Fir, 16 ins. diam., bears N.45 $\frac{1}{2}$ *W., 31 lks. dist. A W. Fir, 10 ins. diam., bears S.69*E., 25 lks. dist.
		Land, rocky and mountainous,; third rate. Timber, Fir, Yew, Cedar and Chinkapin.
East, on random line, between Secs. 9 and 16.		
40.00		Set temporary $\frac{1}{4}$ Sec. post.