

Subdivisions of T. 28 S., R. 8 W.

CHAINS	
	<p>A Fir, 36 ins. diam., bears N.70*W., 97 lks. dist.</p> <p>A Fir, 12 ins. diam., bears S.50*W., 77 lks. dist.</p> <p>A Fir, 30 ins. diam., bears S.60*E., 68 lks. dist.</p> <p>A Laurel, 3 ins. diam., bears N.40*E., 33 lks. dist.</p> <p>Land, broken and third rate.</p> <p>Timber, scattering Fir and Cedar.</p> <p style="text-align: right;">July 30, 1875.</p>
	<p>East, on random line, between Secs. 4 and 9,</p> <p style="text-align: right;">Va.20*30'E.</p>
40.00	Set temporary $\frac{1}{4}$ Sec. post.
80.80	Point, on East boundary, 94 lks. North of post, at cor. of Secs. 3, 4, 9 and 10.
	S.89*20'W. on true line, between 4 and 9.
16.00	Summit of mountain, NW. and SE.
40.40	Set post, 4 ft. long, 4 ins. diam., and 1 ft. in ground for $\frac{1}{4}$ Sec. cor., from which
	A Laurel, 15 ins. diam., bears N.40*W., 34 lks. dist.
	A Fir, 15 ins. diam., bears S.35*W., 35 lks. dist.
55.20	Brook, 10 lks. wide, runs South.
66.70	Grassy ridge, North and South.
80.80	Intersect post, for cor. of Secs. 4, 5, 8 and 9.
	Land, broken and mountainous.
	Timber, good on summit.
	<p>North, on random line, between Secs. 3 and 4,</p> <p style="text-align: right;">Va.20*30'E.</p>
40.00	Temporary $\frac{1}{4}$ Sec. post.
80.40	Intersect North boundary of T., 50 lks. East of cor., a Cedar on steep mountain slope facing South.
	Land, from rolling to broken.
	Timber, very good. Fir, Hemlock, Cedar, etc.
	S.0*22'E. on true line, between Secs. 3 and 4,
	Va.20*30'E.
28.00	Descended to deep ravine, running West.
40.40	Set post, 4 ft. long, 4 ins. diam., 1 ft. in ground for