

## Subdivisions of T. 28 S., R. 8 W.

CHAINS

 $\frac{1}{4}$  Sec. cor., from which

A Hemlock, 10 ins. diam., bears S.75\*E., 48 lks.  
dist.

A Hemlock, 18 ins. diam., bears S.75\*W., 33 lks.  
dist.

72.90 Brook, 4 lks. wide, runs NW.

80.40 Intersect post, at cor. of Secs. 3, 4, 9 and 10.

Land, from rolling to broken.

Timber, very good Fir, Cedar and Hemlock.

July 31, 1875.

North, between Secs. 29 and 30,

Va.20\*30'E.

Began at post to Secs. 29, 30, 31 and 32.

40.00 Set post, 4 ft. long, 4 ins. diam. and 1 ft. in ground,

for  $\frac{1}{4}$  Sec. cor., from which

A Cedar, 20 ins. diam., bears S.50\*E., 60 lks. dist.

A Fir, 20 ins. diam., bears N.45\*W., 120 lks. dist.

50.00 Foot of steep ascent.

80.00 Set post, 4 ft. long, 5 ins. diam., 1 ft. in ground, for

cor. of Secs. 19, 20, 29 and 30, from which

A Fir, 40 ins. diam., bears N.65\*E., 32 lks. dist.

A Fir, 36 ins. diam., bears N.30\*W., 16 lks. dist.

A Fir, 28 ins. diam., bears S.60\*W., 18 lks. dist.

A Hemlock, 10 ins. diam., bears S.55\*E., 11 lks.

dist.

South,  $\frac{1}{2}$  mile, gently rolling.North,  $\frac{1}{2}$  mile, steep and rocky.

Land, mountainous and rocky.

Soil, third rate and gravelly.

Timber, Fir, Cedar and Hemlock, of good quality.

East, on random line, between Secs. 20 and 29,

Va.20\*30'E.

40.00 Set temporary  $\frac{1}{4}$  Sec. post.