

Subdivisions of T. 28 S., R. 8 W.

CHAINS 80.94	Intersect post cor. Secs. 20, 21, 28 and 29.
	West, on true line, between Secs. 20 and 29. Steep ascent.
8.00	Summit of steep slope.
30.50	Point of rocks 40 ft. high on South slope.
35.70	Crossed high point of rocks, facing South.
40.47	Set post, 4 ft. long, 4 ins. diam., 1 ft. in ground for $\frac{1}{4}$ Sec. cor., from which A Fir, 18 ins. diam., bears N.10*W., 28 lks. dist. A Fir, 20 ins. diam., bears S.60*E., 28 lks. dist.
	Begin to descend.
70.00	Steep descent.
80.94	To post 4 ft. long, 5 ins. diam., 1 ft. in ground for cor. of Secs. 19, 20, 29 and 30.
	Land, mountainous and broken.
	Soil, third rate and gravelly.
	Timber, Fir, Cedar and Hemlock of good quality.
	West, on random line, between Secs. 19 and 30, <span style="float: right;">Va.20*30'E.</span>
40.00	Set temporary $\frac{1}{4}$ Sec. post.
80.68	Intersect West boundary 48 lks. South of cor.
	South 89*40'E., on true line, between Secs. 19 and 30, <span style="float: right;">Va.20*30'E.</span>
13.60	Summit.
40.68	Set post, 4 ft. long, 4 ins. diam., 1 ft. in the ground for $\frac{1}{4}$ Sec. cor., from which A Laurel, 24 ins. diam., bears N.35*W., 10 lks. dist. A Fir, 72 ins. diam., bears South, 37 lks. dist.
71.60	Brook, 10 lks. wide, runs South.
80.68	Intersect post at cor. of Secs. 19, 20, 29 and 30.
	Land, mountainous and broken.
	Soil, third rate.