

County Surveyor's Record, Douglas County, Oregon

Resurvey of S. Bdy. T. 27 S., R. 7 W.
(Hathorn Survey)

CHAINS

Land, nearly level.

Soil, clay loam, 1st rate.

Timber, scattering oak and ash.

Undergrowth, ash, willow, and oak.

N. 89°49'W., on S. bdy. of sec. 35.

Over nearly level land, through scattering timber and undergrowth.

0.45 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for witness cor. to the cor. of secs. 35 and 36, with brass cap marked

T27S	R7W	
S35	S36	
		WC
1924		

from which

An oak, 5 ins. diam., bears N. 5°W., 41 lks. dist.,
marked W C T 27 S R 7 W S 35 B T.

No other bearing tree available, stones for mound
not available.

NW. cor. of house, bears S. 35½°E., 2.96 chs. dist.

NW. cor. of barn, bears 78½°E., 3.45 chs. dist.

0.47 Cor. of wire fence, bears S. and W., follows line.
Old rail fence, bears N.

12.00 Point of timber and brush, bears N. and S.

13.75 Creek, 4 lks. wide, course S.; leave timber and brush,
bears n. and S.

39.87 Intersect the ¼ sec. cor. of sec. 35, point determined
by intersection of fences, bearing N., and W.; this
point agrees closely with position by proportionate
measurement and is accepted.

At the exact cor. point

Set an iron post, 3 ft. long 1 in. diam., 28 ins. in the
ground, for ¼ sec. cor. of sec. 35, with brass cap
marked

<u>¼S35</u>

1924

No bearing trees or other objects available. No stones