

County Surveyor's Record, Douglas County, Oregon

10

Resurvey of S. Bdy. T. 27 S., R. 7 W.
(Hathorn Survey)

CHAINS	
	and brush, bears N. and S.
59.72	Looking Glass Creek, 30 lks. wide. course S. Leave valley; ascend E. slope, 100 ft.
67.00	Wire fence, bears N. and S.
70.00	Top of ascent; thence over rollong N. slope.
71.63	Intersect the line bet. secs. 3 and 4, T. 28 S., R. 7 W. Ford's standard cor. of secs. 3 and 4, re-established and hereafter described, bears N. 7°53'W., 94 lks. dist. The $\frac{1}{4}$ sec. cor., hereafter described, bears S. 7°53'E., 41.45 chs. dist.
72.41	Intersect the cor. established by Hathorn as the standard cor. of secs. 3 and 4, located by the record bearing and distance from the stump of the SW. bearing tree. The marks are obliterated by decay, but evidence of the blazes are still distinguishable.
	At the exact cor. point
	Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for angle point, with brass cap marked
	A P
	1924
	from which (new bearing trees)
	A fir, 22 ins. diam., bears N. 60°E., 53 lks. dist.
	marked A P B T.
	A fir, 8 ins. diam., bears N. 76°W., 23 lks. dist.,
	marked A P B T.
	Stump of original SW. bearing tree, an oak, 28 ins. diam., bears S. 56°W., 55 lks. dist.
	The original SE. bearing tree, a laurel, is rotted out.
	Stump hole bears S. 32°E., 42 lks. dist.
	Thence
	S. 89°42'W., continuing my measurements.
79.87	Intersect the cor. of secs. 33 and 34, located by record bearing and distance from the original NE. bearing tree, marks legible. No trace is found of the original NW. bearing tree.
	At the exact cor. point.