

## County Surveyor's Record, Douglas County, Oregon

22

Resurvey S. Bdy. T. 27 S., R. 7 W.  
(Hathorn Survey)

CHAINS

brass cap marked

SW 1/4 S6  
RSW 1/4 R7 1/2 W  
T28S  
1924

from which (new bearing trees)

A fir, 20 ins. diam., bears S.29\*E., 52 lks. dist.,  
marked T 28 S R 7 1/2 W S 6 B T.

A fir, 20 ins. diam., bears S.12\*W., 47 lks. dist.,  
marked T 28 S R 8 W S 1 B T.

Original bearing tree, a black oak, 16 ins. diam., bears  
S.62\*E. (instead of S.61\*E.), 184 lks. dist.

Stump of original bearing tree, a black oak, 10 ins.  
diam., bears S.3\*W. ( instead of S.8\*W.), 44 lks. dist.

Land, rolling.

Soil, clay loam, 2nd rate.

Timber, fir, oak, and pine.

Undergrowth, hazel, laurel, and fir.

Resurvey of sec. 33, T. 27 S., R. 7 W.

Retracements

From the Hathorn cor. of secs. 33 and 34, on the S.bdy.  
of the Tp., North bet. secs. 33 and 34; at 40.01 chs.  
fall 5 lks. E. of the 1/4 sec. cor., and at 79.99 chs.  
fall 3 lks. W. of the cor. of secs.27, 28, 33, and 34.

N.89\*48'W., retracing the line bet. secs. 28 and 33; at  
39.84 Chs. fall 13 lks. N. of the 1/4 sec.cor., and at  
79.77 Chs. fall 29 lks. N. of the cor. of secs.28, 29,  
32 and 33.

South, retracing the line bet. secs. 32 and 33; at 40.05  
chs. fall 3 lks. E. of the 1/4 sec. cor., and at 80.16  
chs. fall 15 lks. W. of the Hathorn cor. of secs. 32  
and 33, on the S. bdy. of T. 27 S., R.7 W.

Note: Sec . 33 is resurveyed to exclude the overlap of  
patented sec. 4, T. 28 S., R. 7 W. on the unpatented  
S 1/4 SW 1/4 of sec. 33.

Commencing at the cor. of secs. 27, 28, 33, and 34, lo-  
cated by measurements from the original bearing trees,  
all found. The SE. tree rotted down and the SW. tree  
badly decayed.