

County Surveyor's Record, Douglas County, Oregon

5857

Resurvey of Sec. 33, T. 27 S., R. 7 W.

CHAINS

Decayed stump of original bearing tree, an oak, bears S.50*W., 59 lks. dist.

No trace is found of original SE. bearing tree.

Land, rolling.

Soil, clay loam, stony in places, 2nd and 3rd rate.

Timber, fir, oak, pine, and laurel.

Undergrowth, chaparral, manzanita; oak, laurel, and fir.

S.0*03*W., bet. secs. 32 and 33.

Over rolling land, through dense timber and medium undergrowth.

Ascend gradually 96 ft. on NW. slope.

18.10 Pole fence, bears NE. and SW.

19.35 Pole fence, bears NW. and SE.

20.00 A house, bears East, 5.00 chs. dist.

25.10 Cor. of fences, bearing NE. and SE.

25.54 Old road, bears NW. and SE.

26.00 Top of spur, slopes SW.; descend 225 ft. on S. slope, to Creek.

40.03 Intersect the $\frac{1}{4}$ sec. cor., located by record bearing and distance from stump hole of original NE. bearing tree, dead, down, and rotten. Marks are legible on the overgrowth. No trace found of the original NW. bearing tree.

At the exact cor. point

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked

$\frac{1}{4}$
 S32 S33
 AP 4
 1924

from which (new bearing trees)

A white oak, 6 ins. diam., bears S.29*E., 32 lks. dist., marked $\frac{1}{4}$ S 33 B T.

A fir, 30 ins. diam., bears N.20*W., 10 lks. dist., marked $\frac{1}{4}$ S 32 B T.

Bearing of old NE. stump hole is N.62*E., 13 lks. dist.