

## County Surveyor's Record, Douglas County, Oregon

Daniel Huntley Donation Land Claim, Nos. 38 and 43,  
Tps. 27 and 28 S., R. 7 W.

CHAINS 52.36	Intersect line bet. secs. 33 and 34, S.0°04'E., 10.35 chs. from the $\frac{1}{2}$ sec. cor.
57.00	Draw course S.
64.63	Intersect NW. cor. of claim No. 38, designated by me as Cor. No. 2, which has been restored by county survey and is a steel plow point driven in ground; from which (new bearing trees) <p style="margin-left: 40px;">A laurel, 9 ins. diam., bears S.25<math>\frac{1}{2}</math>°E., 97 lks. dist., marked A P 2 D L C 38 B T.</p> <p style="margin-left: 40px;">A black oak, 16 ins. diam., bears S. 74<math>\frac{1}{2}</math>°E., 160 lks. dist., marked A P 2 D L C 38 B T.</p> <p style="margin-left: 40px;">Original bearing tree, a white oak, 30 ins. diam., bears S.72<math>\frac{1}{2}</math>°E., 224 lks. dist., old blaze visible.</p> <p style="margin-left: 40px;">Land, rolling.</p> <p style="margin-left: 40px;">Soil, clay loam, 1st and 2nd rate.</p> <p style="margin-left: 40px;">Timber, oak, laurel, and pine.</p> <p style="margin-left: 40px;">Undergrowth, laurel and oak.</p>
	S.0°05'E., on a true line, along the W. bdy. of claim 38. Over rolling mountainous land, through scattering timber and dense undergrowth.
5.45	Descend 91 ft. on S. slope, along fence, bears S. Wire fence, bears E. and W.
5.90	Looking Glass-Reston road, bears E. and W.
6.20	Fence, bears E. and W.; enter open meadow.
17.00	Leave meadow, bears E. and W.; enter timber and brush.
18.75	Looking Glass Creek, 25 lks. wide, course E.; ascend 236 ft. on N. slope.
28.31	Intersect Ford's N. bdy. of sec. 4, 13.00 chs. N.88°55' W. from the cor. established for cor. of secs. 33 and 34, restored as angle point, hereafter described.
29.64	Intersect Hathorn's S. bdy. of sec. 33, 12.26 chs. N.89°38' W, of the cor. of secs. 33 and 34, heretofore described.