

## County Surveyor's Record, Douglas County, Oregon

Daniel Huntley Donation Land Claim, Nos. 38 and 43  
Tps. 27 and 28 S., R. 7 W.

31

## CHAINS

39.92

Intersect the SW. cor. of claim No 43. designated by me as cor. No. 3, which is a cedar post, 4x4 ins. square, set in a mound of stone, restored by county survey.

I take one new bearing tree; From the cor.

A fir, 16 ins. diam., bears N.49\*E., 29 lks.dist., marked A P 3 D L C 43 B T.

Original bearing tree, a black oak, 48 ins.diam., bears N.85\*E., 65 lks. dist., old blaze opened and marks plain.

Land, rolling and mountainous.

Soil, clay loam, 1st and 2nd rate.

Timber, fir, oak, and laurel.

Undergrowth, hazel, laurel, and oak.

Note: The next three lines of claim No. 43 are not retraced by me, but the field notes of a recorded county survey made in 1893 exhibit the following:

From the SW. cor. (Cor.No.3)

East.

20.20

Intersect line bet. secs. 3 and 4, 11.10 chs. S. of cor.

Note: This intersection is erroneous, as the surveyor is evidently not aware of the distortion of the section line. The county survey is tied to Ford's cor. of secs. 3 and 4, which was restored.

39.38

Set new post, original bearing tree standing.

A black oak, 24 ins. diam., bears N.70\*E., 11 lks. dist.

South

25.00

Rock cor., original bearing tree down, stump remains:

A white oak, 30 ins. diam., bears N. 46\*E., 879 lks. dist.

East

25.12

Rock cor., original bearing tree stump standing:

A white oak, 12 ins. diam., bears N.35\*W., 184 lks. dist.