

Daniel Huntley Donation Land Claim, Nos. 38 and 43
Tps. 27 and 28 S., R. 7 W.

CHAINS

I resume retracement at the last above mentioned cor., which I designate as Cor. No 6, which is identified by intersection of center line of road with fence line bearing W. The Rock cor. has been removed or buried in the construction of the road. No trace is now found of the original bearing tree. Cor. not re-monumented.

Thence

N.0*02'W., along the E. bdy. of claim 43.

Along road, bears N. and S.

7.20 Center of covered bridge across Looking Glass Creek; creek, 25 lks. wide, course E.

35.20 Intersect Hathorn's S. bdy. of sec. 34, 12.50 chs. S89*50'E. of $\frac{1}{4}$ sec. cor., heretofore described.

35.97 Intersect Ford's N. bdy. of sec. 3, 5.25 chs. S.89*47'E. of $\frac{1}{4}$ sec. cor., hereafter described.

64.90 Intersect cor. No. 1, Claim No. 38, heretofore described.

Land, nearly level.

Soil, clay loam, 2nd rate.

No timber or undergrowth.

Resurvey of N. Bdy. T. 28 S., R.7 W. (6th Std. Par. S.)
(Ford Survey)

I commence at the standard cor. of Tps. 28 S., Rs. 6 and 7 W., established by Elder and Gile in 1853, the point for which is located by record bearing and distance from the SW. original bearing tree, a black oak, 24 ins. diam.; bears S.24 $\frac{1}{2}$ *W., 75 lks. dist., blazes open and marks legible. I re-mark this tree S C T 28 S R 7 W S 1 B T. The SE. bearing tree has rotted away, but stump hole indicating its position, bears S.57 $\frac{1}{2}$ *E. 70 lks. dist.

At the exact cor. point

Set an iron post, 3 ft. long, 3 ins. diam., 27 ins. in the ground, for standard cor. of Tps. 28 S., Rs. 6 and 7 W., with brass cap marked