

County Surveyor's Record, Douglas County, Oregon

Resurvey of N. Bdy. T. 28 S., R. 7 W. (6th Std. Par. S.)
(Ford Survey)

CHAINS

29.10 Creek, 5 lks. wide, course SW.

40.08 Point for Ford's standard cor. of secs. 1 and 2, located by
Hathorns record tie from the cor. of secs. 35 and 36.

At the exact cor. point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in
the ground, for standard cor. of secs. 1 and 2, with
brass cap marked

S2:S1
T28S:R7W
SC
1924

from which

NE. cor. of barn bears S.73 $\frac{1}{4}$ *W.

NW. cor. of barn bears S.75*W.

NW. cor. of house bears S.64 $\frac{1}{2}$ *W.

Point for Hathorn's cor. of secs. 35 and 36, heretofore
described, bears S.86*11'W., 7.38 chs. dist.

Land, nearly level.

Soil, clay loam, 1st rate.

Timber, scattering oak and ash.

Undergrowth, ash, willow, and oak.

N.89*51'W., along the N. bdy. of sec. 2.

Over level land, in orchard.

6.90 Wire fence, bears N. and S.; leave orchard, cross road.

7.83 Old rail fence, bears N. and S.

18.90 Point of timber and brush, bears N. and S.

20.65 Creek, 4 lks. wide, course S.; leave timber and brush,
bears N. and S.

39.93 Point for Ford's standard $\frac{1}{2}$ sec. cor., located by Hathorn's
record tie from the $\frac{1}{2}$ sec. cor. of sec. 35.

At the exact cor. point

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the
ground, for standard $\frac{1}{2}$ sec. cor., with brass cap marked

SC $\frac{1}{2}$ S2
1924

No bearing trees or other available objects, no
stones available for mound.

Hathorn's $\frac{1}{2}$ sec. cor. of sec. 35, heretofore described,
bears S.86*24'W., 7.31 chs. dist.