

## County Surveyor's Record, Douglas County, Oregon

40

Resurvey of N. Bdy. T. 28 S., R. 7 W. (6th Std. Par.S.)  
(Ford Survey)

## CHAINS

A fir, 8 ins. diam., bears S.79\*E., 48 lks. dist.

Marked A P B T.

A fir, 18 ins. diam., bears S.56\*W., 40 lks. dist.,

marked A P B T.

Original NE. bearing tree, a white oak stump, bears N.70\*  
E., 20 lks. dist.Original NW. bearing tree, a black oak stump, bears N.53\*  
W., 35 lks. dist.The cor. established by Hathorn for  $\frac{1}{4}$  sec. cor. of sec.  
33, restored as  $\frac{1}{4}$  sec. cor. and angle point No.10 of  
resurveyed Sec. 33, T. 27 E., R. 7 W., heretofore de-  
scribed, bears S.36\*43'W., 2.26 chs. dist.

Thence, from the angle point,

N.87\*38'W., along the N. bdy. of sec. 4.

Ascend NE. slope, 140 ft. to bench.

1.35 Intersect center meridional subdivision line of original  
sec. 33, and angle point No. 9 of resurveyed sec.33  
heretofore described.Hathorn's  $\frac{1}{4}$  sec. cor. of sec. 33, heretofore described,  
bears S.0\*04'W., 1.87 chs. dist.

14.75 Road, bears N. and S.

16.35 Top of ascent on bench sloping gently to N.

17.70 Fence, bears N. and S.

22.40 Dry draw, course NE.; ascend E. slope, 200 ft.

31.31 Intersect the point for standard cor. of secs. 4 and 5,  
established by Ford, located by record bearing and  
distance from the original SW. bearing tree, blazes  
distinct, but marks weathered and decayed away. SE.  
bearing tree has rotted away.

At the exact cor. point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in  
the ground, for standard NW. cor. of sec. 4 only, with  
brass cap markedS4  
T28S  
R7W  
SC  
1924