

County Surveyor's Record, Douglas County, Oregon

Resurvey of N. Bdy. T. 28 S., R. 7 W. (6th Std. Par.S.)
(Ford Survey)

CHAINS

71.71

Intersect the point for standard cor. of Tps. 28 S., Rs. 7 and 8 W., established by Ford, located by Hathorn's record tie from the Hathorn standard cor. of Tps. 28 S., Rs. 7 and 8 W., then corrected to true position with reference to the original SW. bearing tree. This tree has fallen and is decayed to such an extent that the marks are gone and could not be positively identified without the Hathorn tie. No evidence could be found of the SE. bearing tree.

At the exact cor, point

Set an iron post, 3 ft. long, 3 ins. diam., 27 ins. in the ground, for standard NW. cor. of T. 28 S..R. 7 W. only, with brass cap marked.

S6
T28S
R7W
SC
1924

from which (new bearing trees)

A white oak, 9 ins, diam., bears S.41½°E., 170 lks. dist., marked S C T 28 S R. 7 W S 6 B T.

A fir, 10 ins. diam., bears S.8°E., 108 lks. dist. marked S C T 28 S R. 7 W S 6 B T.

Original bearing tree, stump hole of black oak, bears S.35°W., 130 lks. dist.

Standard cor. of Tps. 28 S., Rs. 7 and 8 W., established by Hathorn, now restored as cor. of Tps. 28 S., Rs. 7½ and 8 W., heretofore described, bears S. 33°48'W., 10.55 chs dist.

Land, rolling.

Soil, clay loam, 2nd rate.

Timber, fir, oak, and pine.

Undergrowth, hazel, laurel, and fir.