

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 28 S., R. 7 W.

CHAINS
12.53

Fence, bears N.10*W. and S.10*E.

17.85

Draw, course SE.; ascend SW. slope, 420 ft.

20.67

Board fence, bears E. and W.

22.60

Draw, course SW.

39.39

Intersect the point for cor. of secs. 19, 20, 29, and 30, located by measurement from the original bearing trees, on which the blazes are plain and some marks visible. The SE. bearing tree could not be found.

At the exact cor. point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for cor. of secs. 19, 20, 29 and 30, with brass cap marked

T28S | R7W
S19 | S20
S30 | S29
1924

from which (original bearing trees)

A pine, 36 ins. diam., bears N.67*E., 23 lks. dist., (now dead and fallen)

A black oak, 16 ins. diam., bears S.26*W., 27 lks. dist.

A black oak, 30 ins. diam., bears N.23*W., 29 lks. dist., re-marked T 28 S R 7 W S 19 B T.

New bearing trees:

A fir, 20 ins. diam., bears N.1*E., 46 lks. dist., marked T 28 S R 7 W S 20 B T.

A fir, 8 ins. diam., bears S.15*E., 13 lks. dist., marked T 28 S R 7 W S 29 B T.

A fir, 16 ins. diam., bears S.78*W., 11 lks. dist., marked T 28 S R 7 W S 30 B T.

Land, level, rolling, and mountainous.

Soil, clay loam, 1st and 2nd rate.

Timber, oak, pine, fir, and laurel.

Undergrowth, oak, hazel, fir, and laurel.

N.87*58*W., bet. secs. 19 and 30.

Over mountainous land, through heavy timber and under-