

County Surveyor's Record, Douglas County, Oregon

5889
57

Subdivisions, T. 28 S., R. 7 W.

CHAINS

From the standard cor. of secs. 3 and 4, on the N. bdy.
of the Tp., heretofore described,

S.7*53'E., bet. secs. 3 and 4.

Over rolling land, through heavy timber and dense under-
growth.

Ascend NE. slope, 226 ft.

0.94 Intersect the S. bdy. of T.27 S., R. 7 W., 78 lks. S.89*
50'E. from the Hathorn standard cor. of secs. 3 and 4,
restored as angle point, heretofore described.

7.00 Slope changes to NW.

10.90 Top of spur, slopes NE.; descend general SE. slope 171
ft.

11.27 Intersect the S. bdy. of the Daniel Huntley D.L.C. No.
43, East, 21.91 chs. from the SW. cor. thereof, hereto-
fore described.

32.60 Old road, bears NE. and SW.; leave timber; enter clearing,
same bearing.

37.10 Leave clearing, bears E. and W.

37.80 Dry draw, course S.60*W.; ascend NE. slope.

42.39 Intersect the $\frac{1}{4}$ sec. cor., which is a 1 in. iron pipe, 2
ins. above ground, set by county surveyor; from which
(Ford's original bearing trees)

A black oak stump, bears N.15*E., 70 lks. dist.(not
N.25*E.), burnt down.

A black oak, 24 ins. diam., bears N.67*W., 146 lks.
dist, (not N.75*W., 147 lks.); this tree has been
cut down, marks are legible on the stump.

New bearing trees marked by county surveyor:

A fir, 10 ins. diam., bears S.65*W., 76 lks. dist.,
marked $\frac{1}{4}$ S C S B T.

A black oak, 20 ins. diam., bears N.53 $\frac{1}{2}$ *W., 245 lks.
dist., marked $\frac{1}{4}$ S C S B T.

Thence from the $\frac{1}{4}$ sec. cor.

S.0*04'E., bet. secs. 3 and 4.

Descend very gradual SE. slope, along woven wire fence.

14.00 Draw, course NE.; ascend NW. slope, 141 ft.