

County Surveyor's Record, Douglas County, Oregon

Resurvey of E. Bdy. T. 28. S., R. 8 W.
(Hathorn Survey)

CHAINS

S.0*07'W., along the E. bdy. of sec. 1.

Over rolling mountainous land, through heavy timber and dense undergrowth.

Ascend NE. slope, 58 ft. along fence.

7.95 Top of low ridge, bears NW. and SE.; descend over SW. slope, 138 ft.

22.00 Dry draw, course SE.; ascend 14 ft.

23.45 Descend SW. slope 84 ft.

26.80 Road, bears E. and W.

28.90 Looking Glass Creek, 25 lks. wide, course E.; ascend gradual N. slope, 98 ft.

40.04 Apportioned distance,

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked

S1 S6
R7 $\frac{1}{2}$
1924

from which

A chinquapin, 8 ins. diam., bears N.87*E., 26 lks. dist., marked $\frac{1}{4}$ S 6 R 7 $\frac{1}{2}$ B T.

A fir, 12 ins. diam., bears N. 78*W., 75 lks. dist., $\frac{1}{4}$ S 1 B T.

Note: At $\frac{1}{4}$ sec. cors. referring to T. 28 S., R.7 $\frac{1}{2}$ W. the marks R 7 $\frac{1}{2}$ are placed upon corners and bearing trees to distinguish these cors. from cors. referring to old secs. of the same designation, of T. 28 S., R. 7 W.

Continue ascent of N. slope 114 ft.

47.40 Top of small spur, slopes NE.; descend 15 ft.

51.40 Ascend N. slope, 162 ft.

73.55 Top of ridge, bears E. and W.; descend SE. slope, 69 ft.

80.08 Intersect the point for cor. of secs. 1, 6, 7, and 12, located by record measurements from the SE., SW., and NW. bearing trees. The NE. tree has rotted away and the SE. tree is now dead.

At the exact cor. point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 1, 6, 7, and 12, with