

County Surveyor's Record, Douglas County, Oregon

Resurvey Of E.Bdy. T. 28 S., R. 8 W.
[Hathorn Survey]

X

CHAINS

From the $\frac{1}{4}$ sec. cor.

S.0°08'W., along the E. bdy. of sec. 13.

Descend S. slope, 48 ft.

1.31 Stream, 3 lks. wide, course S.60°E.; ascend NE. slope, 480 ft.

18.70 Draw, course NE.; ascend over N. slope.

24.89 Top of ridge, bears E. and W.; descend SW. slope, 65 ft.

37.85 Stream, 2 lks. wide, course NW.; ascend NE. slope, 37 ft.

39.91 Intersect the point for cor. of secs. 13, 18, 19, and 24, located by record measurement from the original SW. and NW. bearing trees upon which the old blazes are plain. The NE. tree is gone and the SE. tree has rotted down, but the marks are still legible.

At the exact cor. point

Set an iron post, 3 ft long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 13, 18, 19, and 24, with brass cap marked

T28S
R8W:R7 $\frac{1}{2}$ W
S13:S18
S24:S19
1924

from which (new bearing trees)

A fir, 20 ins, diam., bears N.3°E., 57 lks. dist., marked T 28 S R 7 $\frac{1}{2}$ W S 18 B T.

A laurel, 36 ins. diam., bears S 43°E., 43 lks. dist., marked T 28 S R 7 $\frac{1}{2}$ W S 19 B T.

Original bearing tree, a laurel, 36 ins. diam., bears S.89 $\frac{3}{4}$ °W., 35 lks. dist., re-marked T 28 S R 8 W S 24 B T.

Original bearing tree, a laurel, 30 ins. diam., bears N.45°W., 65 lks. dist., re-marked T 28 S R 8 W S 13 B T.

Land, mountainous.

Soil, clay loam, 2nd and 3rd rate.

Timber, fur, oak, and laurel.

Undergrowth, hazel, laurel, oak, and fir.