

County Surveyor's Record, Douglas County, Oregon

5917

Resurvey of E.Bdy. T.28 S., R. 8 W.  
(Hathorn Survey)

X

CHAINS	
	S.0°12'W., along the E. bdy. of sec. 24. Over mountainous land, through heavy timber and dense undergrowth. Ascend along W. slope, 124 ft.
10.55	Top of spur, slopes SW.; descend rocky SE. slope, 750 ft. through scattering oak timber.
34.25	Dry rocky ravine, course SW.; ascend NW. slope, 62 ft.
37.00	Point of spur, slopes SW.; descend S. slope, 85 ft.
39.49	Point for $\frac{1}{4}$ sec. cor., located 43 lks. N. of the witness $\frac{1}{4}$ sec. cor., hereafter described. At the true cor. point, which falls on solid bedrock covered with 6 ins. of soil, I mark a cross (x) $\frac{1}{4}$ on the bedrock, over which set a basalt stone, 20x12x6 ins., surrounded with a mound of stone and earth, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on W. face; from which A black oak, 8 ins. diam., bears S.15°E., 39 lks. dist., marked $\frac{1}{4}$ S 19 R 7 $\frac{1}{2}$ B T. A black oak, 8 ins. diam., bears S.28°W., 30 lks. dist., marked $\frac{1}{4}$ S 24 B T. Thence from the $\frac{1}{4}$ sec. cor. S.0°19'W., along the E. bdy. of sec. 24.
0.43	Intersect the point for the witness cor. to the $\frac{1}{4}$ sec. cor., located by record bearing and distance from the original SW. bearing tree, which is a black oak snag, bears S.75°W., 73 lks. dist., marks still legible. The NE. bearing tree has fallen, but the marks are still legible. The witness cor. is not restored. Continue descent.
0.80	Draw, course W., water in pools; ascend NW. slope, 48 ft.
2.55	Top of spur, slopes W.; descend SW. slope, 59 ft.
6.80	Draw, course NW.; ascend NW. slope, 350 ft.
12.55	Board fence, bears N.30°W. and S.30°E.
16.38	Fence, bears NE. and SW.
28.10	Point of spur, slopes W.; ascend along W. slope.
31.60	Top of spur, slopes SW.; descend S. slope, 120 ft.