

County Surveyor's Record, Douglas County, Oregon

Resurvey of E. Bdy. T 28 S., R. 8 W.
(Hathorn Survey)

CHAINS

39.79 Intersect the point for cor.. of secs. 19, 24, 25, and 30,
located by record measurement from the original bearing
trees.

At the exact cor. point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the
ground, for cor. of secs. 19, 24, 25, and 30, with
brass cap marked

T28S
R8W:R7½W
S24:S19
S25:S30
1924

from which (new bearing trees)

A fir, 10 ins. diam., bears N.46*E., 26 lks. dist.,
marked T 28 S R 7½ W S 19 B T.

A fir, 20 ins. diam., bears S.54*E., 30 lks. dist.,
marked T 28 S R 7½ W S 30 B T.

A fir, 12 ins. diam., bears S.37*W., 29 lks. dist.,
marked T 28 S R 8 W S 25 B T.

A fir, 14 ins. diam., bears N.14*W., 19 lks. dist.,
marked T 28 S R 8 W S 24 B T.

Original bearing tree, a black oak, 36 ins. diam., bears
N.58*E., 30 lks. dist., marks legible.

Original bearing tree, a black oak, 24 ins. diam., bears
S.72*E., 75 lks. dist., blazes plain.

Original bearing tree, a black oak, snag, bears S.65*W.
(not S.72*W.), 30 lks. dist., marks rotted away.

Original bearing tree, a black oak, rotted down, stump
hole shows position, bears N.11*W. (not N.18*W.), 38
lks. dist.

Land, mountainous.

Soil, rocky 4th rate.

Timber, fir, and oak.

Undergrowth, oak and fir.

S.0*32*W., along the E. bdy. of sec. 25.

Over mountainous land, through scattering timber and