


County Surveyor's Record, Douglas County, Oregon

Resurvey of E.Bdy. T.28 S., R. 8 W.
(Hathorn Survey)

CHAINS

Set an iron post, 3 ft. long, 3 ins. diam., 27 ins. in the ground, for cor. of T. 28 S., R. 7½ W., with brass cap marked




In cultivated field, no accessories available.

- 17.50 Small draw, course SE.
19.25 NW. cor. of a barn.
21.40 Board fence, bears NW. and SE.; leave grain field.
21.70 Road, bears NW, and SE.
22.95 Fence, bears NW. and SE.; enter grain field.
23.42 Intersect the line bet. secs. 30 and 31, T. 28 S., R. 7 W., S.88°23'E., 45 lks. from the Ford cor. of secs. 25, 30, 31, and 36, hereafter described.

At the point of intersection

Set an iron post, 3 ft. long, 2 in. diam., 27 ins. in the ground, for resurvey cor. of secs. 30 and 31, T. 28 S., R. 7 W., with brass cap marked



from which (trees marked by county surveyor)

A white oak, 36 ins. diam., bears N.82½°E., 976 lks. dist., marked C S T 28 S R 7 W S 30 B T.

A white oak, 24 ins. diam., bears S.70°E., 811 lks. dist., marked C S T 28 S R 7 W S 31 B T.

No nearer trees available.

- 40.00 Enter bed of Ten Mile Creek, course NE.
40.19 Intersect true point for Hathorn's cor. of secs. 25, 30, 31, and 36, now in bed of Ten Mile Creek, old cor. and all bearing trees washed out, point identified by county surveyor, who states as follows in recorded field notes: