

County Surveyor's Record, Douglas County, Oregon

5933

Resurvey of W. Bdy. T. 28 S., R. 7 W.  
(Ford Survey)

101

CHAINS

established by Ford, located by record bearing and distance from the original NE. bearing tree, blazes plain, marks grown over, and not opened. Could not find the SE., SW., or NW. bearing trees.

At the exact cor. point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 19 and 30 only, with brass cap marked

T28S  
S19  
S30  
R7W  
1924

from which

A fir, 12 ins. diam., bears S.61\*E., 17 lks. dist., marked T. 28 S R 7 W S 30 B T (New B.T.)

Original bearing tree, a black oak, 30 ins. diam., bears N.33\*E., 44 lks. dist., re-marked T. 28 S R 7 W S 19 B T.

Land, rolling and mountainous.

Soil, clay loam, 2nd rate.

Timber, fir and oak.

Undergrowth, fir, oak, laurel, and hazel.

S.1\*42'W., along the W. bdy. of sec. 30.

Over rolling land, through scattering timber and undergrowth,

Ascend over NW. slope, 138 ft.

5.05 Top of spur, slopes W.; thence along W. slope.

8.05 Top of spur, slopes SW.; descend SE. slope, 333 ft.

17.20 Intersect the cor. of Secs, 19 and 30, T.28 S., R. 7½ W., hereafter described.

33.23 Intersect the point for ¼ sec. cor., established by Ford; two old witness trees are found, evidently marked by Ford, blazes opened, marks plain, do not agree with record. Corner located by Hathorn's tie and old blazes face this point.

At the exact cor. point