

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 29 S., R. 7 W.

5949
 ✓

CHAINS	<p>marked A P 1 TR 49 B T.</p> <p>23.65 Bottom of descent; ascend 162 ft.</p> <p>36.80 Top of ascent; descend 248 ft.</p> <p>45.77 Intersect the W. bdy. of the Tp., at the resurvey cor. of secs. 7 and 18.</p> <p>Original Ford cor. of secs. 7, 12, 13, and 18, on W. bdy., bears N.76°03'W., 2.98 chs. dist.</p> <p>Land, rolling.</p> <p>Soil, clay loam, 2nd rate.</p> <p>Timber, oak, fir, and laurel.</p> <p>Undergrowth, hazel, oak, fir, and laurel.</p> <hr/> <p>From the cor. of secs. 7, 8, 17, and 18</p> <p>S.0°59'W., bet. secs. 17 and 18.</p> <p>Over rolling land, through scattering timber and undergrowth.</p> <p>Ascend NE. slope, 21 ft.</p> <p>4.00 Top of ridge, bears NW. and SE.; descend SW. slope, 95 ft.</p> <p>8.75 Head of draw, course SW.; ascend along W. slope, 50 ft.</p> <p>25.15 Top of spur, slopes SW.; descend SE. slope, 176 ft.</p> <p>39.00 Top of spur, slopes SE.; descend S slope.</p> <p>39.68 Intersect the point for $\frac{1}{4}$ sec. cor., located by measurement from the original bearing trees.</p> <p>At the exact cor. point</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked</p> <p style="text-align: center;">$\frac{1}{4}$ S18:S17 1924</p> <p>from which (the original bearing trees)</p> <p style="padding-left: 40px;">A black oak, 40 ins. diam., bears N.81°E., 82 lks. dist. (not N.77°E.), marks grown over, not opened.</p> <p style="padding-left: 40px;">A black oak, 30 ins. diam., bears S.66$\frac{1}{2}$°W., 57 lks. dist. (not S.40°W., marks grown over, not opened.</p> <p>New bearing trees:</p> <p style="padding-left: 40px;">A black oak, 28 ins. diam., bears S.34°E., 68 lks. dist., marked $\frac{1}{4}$S 17 B T.</p> <p style="padding-left: 40px;">A white oak, 5 ins. diam., bears S.55°W., 55 lks.</p>
--------	--