

County Surveyor's Record, Douglas County, Oregon

5959
127

Subdivisions, T. 29 S., R. 7 W.

+

CHAINS

56.80 Top of spur, slopes E.; descend SE. slope, 178 ft.
 67.40 Creek, 2 lks. wide, course E.; ascend NE. slope, 40 ft.
 68.61 Intersect the S. bdy. of the Tp., at the cor. of secs. 31
 and 32, hereafter described.
 Land, rolling.
 Soil, clay loam; 2nd rate.
 Timber, fir, oak, cedar, and laurel.
 Undergrowth, hazel, fir, oak, and laurel.

From the cor. of secs. 29, 30, 31, and 32.
 S289°37'E., bet. secs. 29 and 32.
 Over rolling land, through heavy timber and dense under-
 growth.

Descend over SE. slope, 136 ft.
 8.50 Draw, course SE.; ascend along S. slope, 64 ft.
 10.70 Pole fence, bears N.80°W. and S.80°E.
 16.60 Top of ascent; descend 60 ft.
 19.30 Road, bears N. and S.
 21.45 Pole fence, bears N. and S.
 24.70 Small draw, course SE.; ascend gradually along S. slope.
 36.95 Descend abrupt SE. slope, 142 ft. to 1/4 sec. cor.
 39.56 Intersect the point for 1/4 sec. cor., located by measure-
 ment from the original bearing trees; marks are plain
 on both trees.

At the exact cor. point
 Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in
 the ground, for 1/4 sec. cor., with brass cap marked

1/4 - $\frac{S29}{S32}$
 1924

from which (the original bearing trees)

A black oak, 24 ins. diam., bears N.45°E., 105 lks.
 dist. (not 225 lks.)

A black oak, 24 ins. diam., bears S.30°E., 180 lks.
 dist.

New bearing trees: