

County Surveyor's Record, Douglas County, Oregon

6003

North Bdy. T. 29 S., R. 8 W.  
(Hathorn Survey)



CHAINS

Ascend SE. slope, 36 ft.

1.40 Point of spur, slopes S.; descend SW. slope, 43 ft.

3.30 Head of draw, course SE.; ascend SE. slope, 66 ft.

6.10 Point of spur, slopes S.; descend SW. slope, 75 ft.

9.95 Old road, bears NW. and SE.

11.00 Draw, course SE.; ascend E. slope, 95 ft.

15.70 Point of spur, slopes NE.; thence along N. slope.

19.00 Top of flat ridge, bears N.10\*E. and S.; descend gradually  
20 ft.

26.60 Bottom of descent; ascend gradually, 98 ft.

39.96 Intersect the point for  $\frac{1}{4}$  sec. cor., located by record  
measurement from the original bearing trees on which  
the blazes are plain.

At the exact cor. point

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in  
the ground, for  $\frac{1}{4}$  sec. cor., with brass cap marked

$\frac{1}{4}$  S36  
S1  
1924

from which (the original bearing trees)

A black oak, 20 ins. diam., bears S.69\*E., 78 lks.  
dist. (not S.61\*E.)

A white oak, 30 ins, diam., bears N.8\*W., 96 lks.  
dist. (not N.10\*W.)

New bearing trees:

A fir, 12 ins. diam., bears N.18\*E., 28 lks. dist.,  
marked  $\frac{1}{4}$  S 36 B T.

A fir, 10 ins. diam., bears S.16\*E., 21 lks. dist.,  
marked  $\frac{1}{4}$  S 1 B T.

Thence from the  $\frac{1}{4}$  sec. cor.

N.89\*59\*W., bet. secs. 1 and 36.

Ascend over SE. slope, 96 ft.

9.50 Top of flat ridge, slopes SE.; descend gradually, 99 ft.

20.60 Pole fence, bears NW. and SE.

33.00 Pole fence, bears N. and S.

40.02 Intersect the point for cor. of secs. 1, 2, 35, and 36,  
located by record measurement from the original