

County Surveyor's Record, Douglas County, Oregon

6013

181

East Bdy. T. 29 S., R. 8 W.
(Hathorn Survey)

CHAINS

48.90 Creek, 10 lks. wide, course SE.; ascend over NE. slope, 526 ft.

51.98 Intersect the line bet. secs. 18 and 19, T. 29 S., R. 7 W., S.75*02'E., 2.97 chs. from the Ford cor. of secs. 13, 18, 19, and 24, restored as cor. No. 3 of Tract No. 52, heretofore described.

At the point of intersection

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for resurvey cor. of secs. 18 and 19, T. 29 S., R. 7 W., with brass cap marked

:T29S
:S18
:S19
:R7W
1924

from which

A fir, 44 ins. diam., bears N.34*E., 42 lks. dist., marked T 29 S R 7 W S 18 B T.

A yew, 10 ins. diam., Bears S.70*E., 12 lks. dist., marked T 29 S R 7 W S 19 B T.

61.15 Draw, course NE.; ascend over NW. slope.

67.35 Perpendicular cliff, 75 ft. high, NW. and SE.

69.45 Top of ridge, bears NW. and SE.; descend SW. slope, 125 ft.

75.95 Head of draw, course SW.

79.73 Intersect the point for the Hathorn cor. of secs. 13, 18, 19, and 24, located by measurement from the original bearing trees. The NE. tree has rotted away, marks on the other trees are grown over and not opened, the blazes are plain.

At the exact cor. point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for cor. of secs. 13 and 24 only, with brass cap marked

T29S:
S13:
~~S24:~~
R8W:
1924

from which (the original bearing trees)