

County Surveyor's Record, Douglas County, Oregon

6019

East Bdy. T. 29 S., R. 8 W.
(Hathorn Survey)

CHAINS

- 29.80 Point of spur, slopes SW.; descend S. slope, 49 ft.
- 32.40 Draw, course SW.; ascend N. slope, 45 ft.
- 34.65 Point of spur, slopes NW.
- 35.90 Draw, course NW.
- 37.80 Draw, course NW.
- 39.98 Intersect the point for Hathorn's cor. of secs. 25, 30, 31, and 36, located by measurement from the positions of the NE. and SW. original bearing trees. These trees have rotted down, but blazes show on the decayed logs, and stump holes evidence their original positions. No evidence is found of the old SE. and NW. bearing trees.

At the exact cor. point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for cor. of secs. 25 and 36 only, with brass cap marked

T29S:
S25:

S36:
R8W:
1924

from which (the original bearing trees)

Stump hole of fir, bears N.48*E., 31 lks. dist.

Stump hole of maple, bears S.58*W., 55 lks. dist.

New bearing trees:

A fir, 48 ins. diam., bears S.42*W., 83 lks. dist., marked T 29 S R 8 W S 36 B T.

A fir, 40 ins. diam., bears N.59*W., 164 lks. dist., marked T 29 S R 8 W S 25 B T.

Land, rolling.

Soil, rocky clay loam, 2nd rate.

Timber, fir, laurel, chinquapin, and pine.

Undergrowth, hazel, laurel, and fir.

S.0*34'E., along the E. bdy. of sec. 36.

Over rolling land, through heavy timber and dense undergrowth.

Ascend over NE. slope, 312 ft.