

County Surveyor's Record, Douglas County, Oregon

6925

Subdivisions, T. 29 S., R. 8 W.

CHAINS

- 1.32 A fir, 40 ins. diam., old line tree, marked with 2 notches on N. and S. sides.
- 4.63 Creek, 8 lks. wide, course NW.; ascend SW. slope, 321 ft.
- 10.15 Point of spur, slopes SW.; along W. slope.
- 11.90 Trail, bears NW. and SE.; ascend SW. slope.
- 30.30 Top of spur, slopes SW.; descend along W. slope, 66 ft.
- 37.65 Bottom of descent; ascend SW. slope, 21 ft.
- 40.05 Intersect the point for $\frac{1}{2}$ sec. cor., located by measurement from the original bearing trees.
- At the exact cor. point
- Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{2}$ sec. cor., with brass cap marked
- S26:S25
1924
- from which (the original bearing trees)
- A black oak, 24 ins. diam., bears S.60*E., 35 lks. dist., marks grown over.
- A laurel, bears N.87*W., 32 lks. dist., rotted down, stump shows position.
- New bearing trees:
- A fir, 14 ins. diam., bears N.61*E., 10 lks. dist., marked $\frac{1}{2}$ S 25 B T.
- A fir, 10 ins. diam., bears N.62*W., 36 lks. dist., marked $\frac{1}{2}$ S 26 B T.
- Thence from the $\frac{1}{2}$ sec. cor.
- N.0*40'E., bet. secs. 25 and 26.
- Descend NW. slope, 110 ft.
- 17.50 Creek, 2 lks. wide, course SW.; ascend over SE. slope, 460 ft.
- 39.71 Intersect the point for cor. of secs. 23, 24, 25, and 26, located by measurement from the original bearing trees.
- At the exact cor. point
- Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for cor. of secs. 23, 24, 25, and 26 with brass cap marked