

County Surveyor's Record, Douglas County, Oregon

6027
195

Subdivisions, T. 29 S., R. 8 W.

CHAINS

39.63 Intersect the point for $\frac{1}{4}$ sec. cor., located by measurement from the original bearing trees.

At the exact cor. point

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked

$\frac{1}{4}$ S24
S25
1924

*FO. 1/10/00
H. Johnson
M 81-75*

from which (the original bearing trees)

A laurel stump (not oak), bears S.50*W., 40 lks. dist., marks are plain on the log.

A laurel stump, bears N.40*W., 13 lks. dist.,

New bearing trees:

A cedar, 10 ins. diam., bears N.6*E., 7 lks. dist., marked $\frac{1}{4}$ S 24 B T.

A cedar, 9 ins. diam., bears S.8*W., 26 lks. dist., marked $\frac{1}{4}$ S 25 B T.

Descend over SE. slope, 477 ft.

56.55 Draw, small spring branch, course N.60*E.; ascend over NW. slope, 166 ft.

69.25 Point of spur, slopes NE.; descend E. slope, 104 ft.

73.95 Head of draw, course N.; ascend NW. slope, 69 ft.

79.54 Intersect the cor. of secs. 24 and 25, on the E. bdy. of the TP., heretofore described.

Land, rolling and mountainous.

Soil, clay loam, 2nd rate.

Timber, fir, hemlock, cedar, and laurel.

Undergrowth, hazel, fir, hemlock, and laurel.

From the cor. of secs. 13 and 24, on the E. bdy. of the Tp.

N.89*57*W., bet. secs. 13 and 24.

Over rolling land, through heavy timber and dense undergrowth.

Descend SW. slope, 32 ft.

0.75 Draw, course NW.