

County Surveyor's Record, Douglas County, Oregon

6043



South Bdy. T. 29 S., R. 7 W.
(Ford Survey)

CHAINS

Timber, fir, pine, laurel, and oak.
Undergrowth, hazel, laurel, and fir.

N.89°40'E., along the S. bdy. of sec 34.

Over rolling land, through heavy timber and dense undergrowth.

Descend SE. slope, 184 ft.

6.15 Broken rocky cliff, 50 ft. high, bears NE. and SW.

9.01 Intersect the cor. of secs. 33 and 34, T. 29½ S., R. 7 W., hereafter described.

11.60 Stream, 4 lks. wide, course SW.; ascend NW. slope, 442 ft.

38.09 Intersect the point for ¼ sec. cor., located by measurement from the original bearing trees.

At the exact cor. point

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for ¼ sec. cor. of sec. 34 only, with brass cap marked

¼ S 34

1924

from which (the original bearing trees)

A laurel, 20 ins. diam., bears S.81.*W., 50 lks. dist. (not S.75*W.), plainly marked overgrowth shows this tree marked 70 years.

A laurel, 36 ins. diam., bears N.15*W. (not N.55*W.), blazes are plain, not opened.

New bearing trees:

A fir, 7 ins. diam., bears N.79*E., 29 lks. dist., marked ¼ S 34 B T.

A fir, 7 ins. diam., bears N.60*W., 3 lks. dist., marked ¼ S 34 B T.

This ¼ sec. cor. is on top of ridge, bears NE. and SW.

Thence from the ¼ sec. cor.

S.88°15'E., along the S. bdy. of sec. 34.

Descend SE. slope, 102 ft.